

PRESSURE VESSEL INSPECTION REPORT

Doc: SGS 560 a Page 1 of 1 Rev 1 b

Lion Breweries Ltd C/- Lion Nathan Shared Services PO Box 90778 AUCKLAND				Customer Ref. : L Serial No. :	8284 Cycle 202 P Air Rec-Between Yeast Rms Chyber Pass, Newmarket
S Satisfactory X Corrective action - not certified		C Inspection comment N Not applicable		A Comment - action at next inspection U Unable to inspect - state reason	
EXTERNAL INSPECTION					
e1 Preparation e2 Shell e3 Coatings (visual only) e4 Welds e5 Nozzles INTERNAL INSPECTION: i1 Shell i2 Welds	C C S S N N	e6 Valves e7 Piping/pumps e8 Manway e9 Bolting e10 Flanges i3 Tube plates i4 Tubes	S	e11 Supports e12 Foundations e13 Earthing e14 Pressure safety valve(s) e15 Pressure gauge e16 Other i5 Nozzles i6 Baffles	S S N C S N
SAFETY VALVE CALIBRA	TION:				
Pressure gauge number PSV Settings (kPa)	Calibration cert number Calibration cert issuer				
NSPECTION COMMENT 1 Preparation: Annual inspenses satisfactory condition			eceivor and was i	nonastad in a cont	

- e2 Shell: Satisfactory condition.
- e3 Coatings (visual only): In good condition.
- e14 Pressure safety valve(s): Visual inspection satisfactory eased ok.

CORRECTIVE ACTIONS:

Type

Agreed Close Out CAR Details

Completed By

: Neil Trilokekar

Signed Off By : Neil Trilokekar

Inspection Date : 12/03/2010

Date Printed : 31/03/2010

THIS CONDITION REPORT DOES NOT CONSTITUTE FORMAL EQUIPMENT CERTIFICATION

SGS is an accredited inspection body (IANZ10) authorised under the provisions of the Health and Safety in Employment (PECPR) Regulations.

This document is issued in accordance with SGS General Conditions for inspection and Testing Services and should be read subject to them (Hard copy available on request or can be viewed at http://www.sgs.com/terms_and_conditions.htm).